2018-19

PROJECT MANAGEMENT COMPLIANCE REPORT

Name of the Client: **Executive Engineer,** Dasarahalli Division, BBMP, Bangalore.

Agency: **Sri. M.S.Venkatesh,** Contractor, Bangalore.

Name of the Work: Improvements of re-asphalting Dasarahalli Main Road & other Roads , S Ramaiash, Ganesha Sawmill, Kempegowda Nagara & Maheshwari Nagara Roads Construction drain and Concrete Main roads &Cross roads of Vidyanagara Dasarahalli Ward No:15&39 (6-works) Package No. DZ 2017-18-(05), BBMP, Bangalore.

PROJECT MANAGEMENT CONSULTANTS

M/s. CIVIL QUALITY CONSULTANTS & ENGINEERS

(Buildings Geo-Tech & Road Materials Testing Laboratory)
An ISO 9001: 2008 Certified Company

#133, Bhuvaneshwarinagar, Dodda Basti Main Road, Bangalore-560056
e-mail: civilqualityconsultants@gmail.com Ph: 8553518550/9886998316

Scanned by CamScanner

Name of Work : Improvements of re-asphalting Dasarahalli Main Road & other Roads , S Ramaiash, Ganesha Sawmill, Kempegowda Nagara & Maheshwari Nagara Roads Construction drain and Concrete Main roads &Cross roads of Vidyanagara Dasarahalli Ward No:15&39 (6-works) Package No. DZ 2017-18-(05), BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** Dasarahalli Division, BBMP, Bangalore.
Contractor/Agency	:	**Sri. M.S.Venkatesh,** Contractor, Bangalore.
Total Cost	:	Rs 219.15Lakhs
Date of Inspection	:	02.04.2019
Status of Bill	:	1st & Final Bill
In the Presence of	:	(a) **Assitant Engineer (Dasarahalli Division),** BBMP, Bangalore.
	:	(b) **Mr. Raghu. H.S,** Engineer M/s Civil Quality Consultants & Engineers, Bangalore.

PMC Compliance Report

Sl. No	Description of the Item		Comments / observations
1	Removing B.S. slab of Drain and stacking.(page No 25., I.no.5.32 of KPWD S.R 2016-17)	:	Work done up to the billed quantity and Quality is satisfactory
2	Earthwork excavation by manulal means in ordinary soil involving an average horizontal throw upto 2 meters and an	:	Work done up to the billed quantity and Quality is satisfactory
3	Refixing B.S. slab of Drain and pointing in C.M (1:3) (Page No.25., I NO.5.33 of KPWD S.R 2016-17)	:	Work done up to the billed quantity and Quality is satisfactory
4	Providing Precast slab of 100mm thick including cost of all materials, labour, curing, transportation, loading, unloading, etc., complete as per the	:	Work done up to the billed quantity and Quality is satisfactory
5	KSRB 500-2: Cleaning the existing Black Topped surface with brooms, soft brushes and finally dusting with old	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ವಿದ್ಯಾನಗರ ಉಪ-ವಿಭಾಗ

Scanned by CamScanner

6	KSRB 500-2: Cleaning the existing Black Topped surface with brooms, soft brushes and finally dusting with old gunny bags and/or compressed air to	:	Work done up to the billed quantity and Quality is satisfactory
7	Providing, laying, spreading and compacting graded stones aggregate to Wet Mix Macadam specifications including pre mixing the material with	:	Work done up to the billed quantity and Quality is satisfactory
8	KSRRB 3000 Filling Pot-holes and Patch Repairs with Bituminous Concrete, 40 mm KSRRB M3000-5. Removal of all failed material, trimming	:	Work done up to the billed quantity and Quality is satisfactory
9	KSRRB M500-7. Providing and applying tack coat using 80/100 grade bitumen(VG10) on the prepared black topped surfaces at 2.5 kg per 10 sqm	:	Work done up to the billed quantity and Quality is satisfactory
10	KSRRB 500-11. Providing and laying bituminous macadam on prepared surface with crushed Coarse aggregates as per design mix formula for base /	:	Work done up to the billed quantity and Quality is satisfactory
11	Providing and laying bituminous concrete 40 mm thick with hot mix plant, using crushed aggregates of specified grading, premixed with	:	Work done up to the billed quantity and Quality is satisfactory
12	Add Plastic to Bituminous Concrete 8% of Bitumen	:	Work done up to the billed quantity and Quality is satisfactory
13	Road marking with Hot Applied Thermoplastic Compound with reflectorising glass beads on bituminous surface:- Providing and laying of hot	:	Work done up to the billed quantity and Quality is satisfactory
14	Providing and fixing Pre cast solid concrete kerb stones made out of CC 1:2:4 with top and bottom width 114 and 165 mm respectively, 400mm high	:	Work done up to the billed quantity and Quality is satisfactory
15	KSRRB 800-1. Painting two coats after filling the surface with synthetic enamel paint in approved shades on new plastered concrete surfaces, with materials, labour complete as per specifications MORTH Chapter 8	:	Work done up to the billed quantity and Quality is satisfactory

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Scanned by CamScanner

16	KSRRB M800-35. Providing and fixing of road stud 100x 100 mm, die- Noscast in aluminium, resistant to corrosive effect of salt and grit, fitted with lense	:	Work done up to the billed quantity and Quality is satisfactory
17	Lead charges for conveying the Exacavated earth including loading and unloading upto 10kms as per directions.	:	Work done up to the billed quantity and Quality is satisfactory

CIVIL QUALITY CONSULTANTS & ENGINEERS Bangalore

Authorised Signatory

For CIVIL QUALITY CONSULTANTS & ENGINEERS

Authorised Signatory

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner